


Uncontained exterior LBP dust and debris photographed after the o/c sponsored lead report of July 8 stated that no disturbed paint existed.





Various LBP hazards throughout the house before and after framing. Now completely hidden by wallboard.





