

Surface preparation matrix for treating glass surfaces

		<u>State of glass surface</u>			
Stage of prep and application	Product and method required	Clean, new, uncontaminated glass	Dirty, uncontaminated glass	Glass that is heavily stained	Etched very badly
Heavy duty clean				✓	A test will determine to what level the surface can be restored to.
Cleanse to remove extreme surface contamination	Sursol Classic with buffing pad - by hand or mechanised			✓	
Deep surface clean	Biowash with standard cleaning materials		✓	✓	
Surface preparation	SilkQuartz preparation wipe	✓	✓	✓	
Surface treatment	SilkQuartz Treatment wipe	✓	✓	✓	
Surface buff	Medium Microfibre	✓	✓	✓	