

```
int sensorPin = 0;
int val = 0;

void setup() {
  Serial.begin(9600);
}

void loop() {
  val = analogRead(sensorPin) / 4;
  Serial.write((byte)val);
  delay(100);
}
```