



# USER DIRECTIONS

**ALWAYS WEAR** • Heat Resistant Gloves • Apron • Safety Glasses

## LOADING

- Rinse off all food particles
- Lift the load basket onto the side hooks
- Place items carefully into the load basket (don't splash)
- Lower the basket slowly into the solution and close the lid
- **DO NOT OVERLOAD WITH HEAVEY EQUIPMENT AS THIS CAN CAUSE BACK INJURY WHEN LOADING OR UNLOADING! Recommend under 10 Kg load**

## UNLOADING

- Lift the load basket slowly onto the side hooks remove items (don't splash)
- **Rinse and scrub all items thoroughly with hot or cold water before leaving to dry**

## SOAKING TIMES

- As per the timetable
- If carbon is still present then scrub, rinse and resoak

Tank temperature should be set at 80 degrees. Do not alter.

## FIRST AID MEASURES

**Contains 70% w/w sodium metasilicate  
UN 3253 Disodium Trioxosilicate, DG 8, P.Gp.III**

### In the Eyes:

Immediately flush with water for at least 15 minutes  
Get Medical Attention Urgently.

### On Skin:

Rinse Well with Water  
Get Medical advice if irritation/burning occurs

### Ingested:

Do not Induce Vomiting  
Rinse Mouth and Drink Water  
Get Medical Attention Urgently

**If in any doubt, contact National Poisons centre 0800 764 766**

LAST SERVICED AT: TIME:                      DATE:	SERVICE AGENT SIGNATURE:
---	--------------------------