


**DIN 7984**  
**ISO 14580 s drážkou TORX**



| Rozměry                                       | M03  | M04  | M05  | M06  | M08      | M10  | M12 |
|---|------|------|------|------|----------|------|-----|
| s   | 2    | 2,5  | 3    | 4    | 5        | 7    | 8   |
| k   | 2    | 2,8  | 3,5  | 4    | 5        | 6    | 7   |
| D   | 5,5  | 7    | 8,5  | 10   | 13       | 16   | 18  |
| $b_1$ ( $L = < 125\text{mm}$ )                | 12   | 14   | 16   | 18   | 22       | 26   | 30  |
| $b_2$ ( $125\text{mm} < L = < 200\text{mm}$ ) | –    | –    | –    | –    | 28       | 32   | 36  |
| $b_3$ ( $L > 200\text{ mm}$ )                 | –    | –    | –    | –    | –        | –    | –   |
| TORX  | TX10 | TX20 | TX25 | TX30 | TX40(45) | TX50 | –   |

| Rozměry                                       | M14 | M16 | M18 | M20 | M22 | M24 |
|---|-----|-----|-----|-----|-----|-----|
| s   | 10  | 12  | 12  | 14  | 14  | 17  |
| k   | 8   | 9   | 10  | 11  | 12  | 13  |
| D   | 21  | 24  | 27  | 30  | 33  | 36  |
| $b_1$ ( $L = < 125\text{mm}$ )                | 34  | 38  | 42  | 46  | 50  | 54  |
| $b_2$ ( $125\text{mm} < L = < 200\text{mm}$ ) | 40  | 44  | 48  | 52  | 56  | 60  |
| $b_3$ ( $L > 200\text{ mm}$ )                 | –   | 57  | 61  | 65  | 69  | 73  |
| TORX  | –   | –   | –   | –   | –   | –   |