

Rasolastik Evo Case Study



Walls were given a brush coat first to provide a key for the trowel coat. Floors were trowel applied.

This residence in New Lynn was suffering from counter thrusting water issues. The client had spent several thousand dollars water proofing the external wall by a third party, but still had issues with water ingress.

Areas were diamond ground to remove paint and laitance. Then the entire area was washed with Fila Deterdek to ensure all free limes and salts were removed. RL80 tape was applied to all floor/wall junctions to provide water tight joints.



Technokolla Rasolastik Evo was then used to water proof the areas due to its ability to handle up to 1.5 bars of counter thrusting pressure. This ensured that the areas were totally waterproofed from future water ingress from the reverse side and negated the failure of the external water-proofing.

- Contractor: **Mayostone**
- Substrate Prep: **Diamond Grinding
Fila Deterdek**
- Waterproofing: **Technokolla Rasolastik Evo**

